Cambium Networks	Document Number	FSB 9076
Cambium Networks Ltd. 3800 Golf Road, Rolling Meadows, IL 60008 U.S.A.	Revision	000v001
FIELD SERVICE BULLETIN	Application	Global
cnPilot Change in Port Binding behaviour starting with software release 4.4	Effective Date	25 March 2019
with software release 4.4	Expiry Date	N/A

FIELD SERVICE BULLETIN

	BULLETIN TYPE	SEVERITY RECOMMENDATION	
	Warranty Service		High – Perform immediately
X	Informational	X	Medium – Perform at next scheduled maintenance
	Customer Specific		Low – Perform when system exhibits symptoms

SUBJECT: Change in Port Binding behaviour starting with software release 4.4

MODEL / SYSTEM AFFECTED: cnPilot-R190, cnPilot-R200, cnPilot-R200P, cnPilot-R201, cnPilot-R201P, cnPilot-R201W

REASON FOR BULLETIN:

Starting with version 4.4 of the Cambium cnPilot R-series software a fix was introduced related to the port binding. This change requires that users creating non-default WAN INTERNET profiles MUST explicitly enable port binding by selecting one or more LAN ports and/or SSIDs to the created INTERNET WAN profile as needed. Software before 4.4 had an issue where in such situations all ports/WLANs were automatically bound to such an INTERNET WAN profile created by the users.

NOTE: Customers using default WAN profile and running firmware 4.3.4 or lower remain unaffected.

NOTE: Customers using non default WAN profile and running 4.3.4 or lower who have explicitly bound their required LAN ports and/or SSIDs to their INTERNET WAN profile will experience no problems after upgrade.

RESOLUTION:

Users running 4.3.4 or lower software and upgrading to 4.4 or newer software MUST ensure that they update their port binding configuration by explicitly selecting one or more LAN ports and/or SSIDs before upgrading to avoid problems related to Internet access from LAN/WLAN clients. For more details refer to the <u>User's Guide</u> and/or <u>Cambium Knowledge Base articles</u> on Port Binding.

If you encounter any issues please open a support ticket with the Cambium support team at the following URL: https://support.cambiumnetworks.com

This Field Service Bulletin is issued by Cambium Networks in line with its policy of continual review and update of product quality, effectiveness and performance. Product performance or quality may be affected if the recommendations contained herein are not implemented, or not implemented as directed. This information is intended for personnel who have the proper tools, equipment and training to perform the tasks as described herein. Copyright © 2019 Cambium Networks, Inc.