Cambium Networks	Document Number	FSB 9083
Cambium Networks, Inc. 3800 Golf Road Schaumburg, IL 60008, U.S.A.	Revision	000v003
FIELD SERVICE BULLETIN	Application	Global
Update cnMaestro Cloud Managed	Effective Date	15 December 2021
Device Software by October 31, 2022 to Prevent Service Loss	Expiry Date	N/A

FIELD SERVICE BULLETIN

	BULLETIN TYPE	SEVERITY RECOMMENDATION	
X	Warranty Service		High – Perform immediately
	Informational	X	Medium – Perform at next scheduled maintenance
	Customer Specific		Low – Perform when system exhibits symptoms

SUBJECT: Update cnMaestro Cloud Managed Device Software by October 31, 2022 to Prevent Service Loss

Software/Configuration AFFECTED: All cnMatrix, cnPilot, Enterprise Wi-Fi 6, ePMP, PMP, and PTP devices managed by cnMaestro Cloud.

Symptom	On November 1, 2022 Cambium will update the certificate for cloud.cambiumnetworks.com to use a new Certificate Authority. All cnMaestro managed devices without the updated Root CA certificate will fail to connect to the cnMaestro Cloud service.

u have questions or concerns please contact Cambium
nical Support at the following: s://www.cambiumnetworks.com/support/contact- ort/
num Software Versions with New Root CA Certificates sted in the table below.

This Field Service Bulletin is issued by Cambium Networks in line with its policy of continual review and update of product quality, effectiveness and performance. Product performance or quality may be affected if the recommendations contained herein are not implemented, or not implemented as directed. This information is intended for personnel who have the proper tools, equipment and training to perform the tasks as described herein. Copyright © 2021 Cambium Networks, Inc.

Cambium Networks	Document Number	FSB 9083
mbium Networks, Inc. 00 Golf Road naumburg, IL 60008, U.S.A.	Revision	000v003
FIELD SERVICE BULLETIN	Application	Global
Update cnMaestro Cloud Managed	Effective Date	15 December 2021
Device Software by October 31, 2022 to Prevent Service Loss	Expiry Date	N/A

	Family	Model	Version
	cnMatrix	cnMatrix EX2K	2.1-r5
		cnPilot R200, R200P	4.6-R16
		cnPilot R201, R201P	4.6-R16
		cnPilot R190V, R190W	4.6-R16
	cnPilot	cnPilot e400/e500	3.11.4.1-r3
		cnPilot e410/e430w/e600	3.11.4.1-r3
		cnPilot R195P	4.7-R6
		cnPilot R195W	4.6-R16
		cnPilot e501S/e502S	3.11.4.1-r3
		cnPilot e700	3.11.4.1-r3
	j	cnPilot e425/e505	4.1-r3
		cnPilot e510	3.11.4.1-r3
	D	Sierra 800	1.1-r3
	cnRanger	Tyndall 101	1.1-r3
	cnReach	N500	5.2.18h
	Enterprise Wi-	XV3-8	6.1-r5
	Fi 6	XV2-2	6.1-r5
	ePMP 1000 Hotspot	ePMP 1000 Hotspot	3.3.1.2-r1
		ePMP 1000, Force 180/200	4.5.0
		ePMP 2000	4.5.0
		ePMP Elevate XM/XW	4.5.0
		ePMP Force 190	4.5.0
		ePMP Force 300	4.5.0
	ePMP	ePMP PTP 550	4.5.0
		ePMP MP 3000	4.5.0
		ePMP PTP 550 E	4.5.0
		ePMP Elevate SXGLITE5	4.5.0
		ePMP Elevate LHG5	4.5.0
		ePMP 3000	4.5.0
	РМР	PMP 450i, PMP 450, PMP 450m, PMP 430 SM	20.0 Beta-6
		PTP 450, PTP 450i, PMP 450 Retro	20.0 Beta-6
		Micro-pop Omni/Sector	20.0 Beta-6
		PTP 650	650-01-50
	PTP	PTP 670 (650 Emulation)	670-01-50,
		1 11 070 (030 Ellidiation)	670-03-12
		PTP 670, PTP 700	700-03-11

This Field Service Bulletin is issued by Cambium Networks in line with its policy of continual review and update of product quality, effectiveness and performance. Product performance or quality may be affected if the recommendations contained herein are not implemented, or not implemented as directed. This information is intended for personnel who have the proper tools, equipment and training to perform the tasks as described herein. Copyright © 2021 Cambium Networks, Inc.